



## Taisnstūra gaisa vadi



Pieejamie izmēri atzīmēti tabulā ar x

H/B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000
100	x																							
150	x																							
200	x	x																						
250	x	x	x	x																				
300	x	x	x	x	x																			
350	x	x	x	x	x	x																		
400	x	x	x	x	x	x	x																	
450	x	x	x	x	x	x	x	x																
500	x	x	x	x	x	x	x	x	x															
600	x	x	x	x	x	x	x	x	x	x														
700	x	x	x	x	x	x	x	x	x	x	x													
800	x	x	x	x	x	x	x	x	x	x	x	x												
900	x	x	x	x	x	x	x	x	x	x	x	x	x											
1000	x	x	x	x	x	x	x	x	x	x	x	x	x	x										
1100	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x									
1200	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x								
1300	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x							
1400	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1500		x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
1600			x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
1700				x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
1800					x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
1900						x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
2000							x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x


# Sānu nobīde



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000	
100	x																								
150	x	x	x	x	x	x	x	x	x	x	x	x	x												
200	x	x	x	x	x	x	x	x	x	x	x	x	x												
250	x	x	x	x	x	x	x	x	x	x	x	x	x												
300	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
350	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
400	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
450	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
500	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
600	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
700	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
800	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
900		x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1000			x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1100				x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1200					x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1300						x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1400							x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1500								x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1600									x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1700										x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1800											x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1900												x	x	x	x	x	x	x	x	x	x	x	x	x	
2000													x	x	x	x	x	x	x	x	x	x	x	x	x


## Taisnstūra līkums 45°



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000	
100	x																								
150	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
200	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
250	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
300	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
350	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
400	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
450	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
500	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
600	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
700	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
800	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
900	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1000	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1100	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1200	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1300	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1400	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1500		x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1600			x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1700				x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1800					x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1900						x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
2000							x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	


## Taisnstūra līkums 90°



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000
100	x																							
150	x	x																						
200	x	x	x																					
250	x	x	x	x																				
300	x	x	x	x	x																			
350	x	x	x	x	x	x																		
400	x	x	x	x	x	x	x																	
450	x	x	x	x	x	x	x	x																
500	x	x	x	x	x	x	x	x	x															
600	x	x	x	x	x	x	x	x	x	x														
700	x	x	x	x	x	x	x	x	x	x	x													
800	x	x	x	x	x	x	x	x	x	x	x	x												
900	x	x	x	x	x	x	x	x	x	x	x	x	x											
1000	x	x	x	x	x	x	x	x	x	x	x	x	x	x										
1100	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x									
1200	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x								
1300	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x							
1400		x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1500			x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1600				x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1700					x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1800						x	x	x	x	x	x	x	x	x	x	x	x	x						
1900							x	x	x	x	x	x	x	x	x	x	x	x						
2000								x	x	x	x	x	x	x	x	x	x	x						


## Taisnstūra pāreja



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000
100	x																							
150	x																							
200	x	x																						
250	x	x	x																					
300	x	x	x	x																				
350	x	x	x	x	x																			
400	x	x	x	x	x	x																		
450	x	x	x	x	x	x	x																	
500	x	x	x	x	x	x	x	x																
600	x	x	x	x	x	x	x	x	x															
700	x	x	x	x	x	x	x	x	x	x														
800	x	x	x	x	x	x	x	x	x	x	x													
900	x	x	x	x	x	x	x	x	x	x	x	x												
1000	x	x	x	x	x	x	x	x	x	x	x	x	x											
1100	x	x	x	x	x	x	x	x	x	x	x	x	x	x										
1200	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x									
1300	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x								
1400		x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x							
1500			x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1600				x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x					
1700					x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x				
1800						x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
1900							x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
2000								x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x


## Pāreja uz apaļo



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000	
100	x																								
150	x																								
200	x	x	x																						
250	x	x	x	x																					
300	x	x	x	x	x																				
350	x	x	x	x	x	x																			
400	x	x	x	x	x	x	x																		
450	x	x	x	x	x	x	x	x																	
500	x	x	x	x	x	x	x	x	x																
600	x	x	x	x	x	x	x	x	x	x															
700	x	x	x	x	x	x	x	x	x	x	x														
800	x	x	x	x	x	x	x	x	x	x	x	x													
900	x	x	x	x	x	x	x	x	x	x	x	x	x												
1000	x	x	x	x	x	x	x	x	x	x	x	x	x	x											
1100	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x										
1200	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x									
1300	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x								
1400		x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1500			x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1600				x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1700					x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1800						x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1900							x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
2000								x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	


## Sānu pievienojums plaknei



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000	
100	x																								
150	x																								
200	x	x	x																						
250	x	x	x	x																					
300	x	x	x	x	x																				
350	x	x	x	x	x	x																			
400	x	x	x	x	x	x	x																		
450	x	x	x	x	x	x	x	x																	
500	x	x	x	x	x	x	x	x	x																
600	x	x	x	x	x	x	x	x	x	x															
700	x	x	x	x	x	x	x	x	x	x	x														
800	x	x	x	x	x	x	x	x	x	x	x	x													
900	x	x	x	x	x	x	x	x	x	x	x	x	x												
1000	x	x	x	x	x	x	x	x	x	x	x	x	x	x											
1100	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x										
1200	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x									
1300	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x								
1400		x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1500			x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1600				x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1700					x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1800						x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
1900							x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
2000								x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x


# Sānu pievienojums



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1300	1400	1500	1600	1700	1800	1900	2000
100	x																							
150		x	x	x	x	x	x	x	x	x	x	x	x											
200			x	x	x	x	x	x	x	x	x	x	x											
250				x	x	x	x	x	x	x	x	x	x											
300					x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
350						x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
400							x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
450								x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	
500									x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
600										x	x	x	x	x	x	x	x	x	x	x	x	x	x	x
700											x	x	x	x	x	x	x	x	x	x	x	x	x	x
800												x	x	x	x	x	x	x	x	x	x	x	x	x
900													x	x	x	x	x	x	x	x	x	x	x	x
1000														x	x	x	x	x	x	x	x	x	x	x
1100															x	x	x	x	x	x	x	x	x	x
1200																x	x	x	x	x	x	x	x	x
1300																	x	x	x	x	x	x	x	x
1400																		x	x	x	x	x	x	x
1500																			x	x	x	x	x	x


# Gala vāks



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200
100	x															
150	x															
200	x	x	x													
250	x	x	x	x												
300	x	x	x	x	x											
350	x	x	x	x	x	x										
400	x	x	x	x	x	x	x									
450	x	x	x	x	x	x	x	x								
500	x	x	x	x	x	x	x	x	x							
600	x	x	x	x	x	x	x	x	x	x						
700	x	x	x	x	x	x	x	x	x	x	x					
800	x	x	x	x	x	x	x	x	x	x	x	x				
900		x	x	x	x	x	x	x	x	x	x	x	x			
1000			x	x	x	x	x	x	x	x	x	x	x	x		
1100				x	x	x	x	x	x	x	x	x	x	x	x	
1200					x	x	x	x	x	x	x	x	x	x	x	
1300						x	x	x	x	x	x	x	x	x	x	
1400							x	x	x	x	x	x	x	x	x	
1500								x	x	x	x	x	x	x	x	
1600									x	x	x	x	x	x	x	
1700										x	x	x	x	x	x	
1800											x	x	x	x	x	
1900												x	x	x	x	
2000												x	x	x	x	


## Gala vāks ar sietu



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200
100	x															
150	x															
200	x	x	x													
250	x	x	x	x												
300	x	x	x	x	x											
350	x	x	x	x	x	x										
400	x	x	x	x	x	x	x									
450	x	x	x	x	x	x	x	x								
500	x	x	x	x	x	x	x	x	x							
600	x	x	x	x	x	x	x	x	x	x						
700	x	x	x	x	x	x	x	x	x	x	x					
800	x	x	x	x	x	x	x	x	x	x	x	x				
900																
1000				x	x	x	x	x	x	x	x	x	x	x	x	
1100					x	x	x	x	x	x	x	x	x	x	x	
1200						x	x	x	x	x	x	x	x	x	x	x
1300						x	x	x	x	x	x	x	x	x	x	x
1400						x	x	x	x	x	x	x	x	x	x	x
1500							x	x	x	x	x	x	x	x	x	x
1600							x	x	x	x	x	x	x	x	x	x
1700								x	x	x	x	x	x	x	x	x
1800								x	x	x	x	x	x	x	x	x
1900									x	x	x	x	x	x	x	x
2000									x	x	x	x	x	x	x	x


## Droseles



Pieejamie izmēri atzīmēti tabulā ar x

H\B	200	250	300	350	400	500	600	700	800	1000	1200	1400
300	x	x	x	x	x	x	x	x				
400	x	x	x	x	x	x	x	x	x			
500	x	x	x	x	x	x	x	x	x			
600	x	x	x	x	x	x	x	x	x			
700	x	x	x	x	x	x	x	x	x			
800	x	x	x	x	x	x	x	x	x	x		
1000	x	x	x	x	x	x	x	x	x	x	x	
1200	x	x	x	x	x	x	x	x	x	x	x	
1400			x	x	x	x	x	x	x	x	x	


## Trokšņu slāpētāji



Pieejamie izmēri atzīmēti tabulā ar x


HxB	300	400	500	600	700	800	900	1000	1100	1200	1300	1400	1500
300	x	x	x	x	x	x	x	x	x	x	x	x	x
400	x	x	x	x	x	x	x	x	x	x	x	x	x
500	x	x	x	x	x	x	x	x	x	x	x	x	x
600	x	x	x	x	x	x	x	x	x	x	x	x	x
700	x	x	x	x	x	x	x	x	x	x	x	x	x
800	x	x	x	x	x	x	x	x	x	x	x	x	x
900	x	x	x	x	x	x	x	x	x	x	x	x	x
1000	x	x	x	x	x	x	x	x	x	x	x	x	x
1100	x	x	x	x	x	x	x	x	x	x	x	x	x
1200	x	x	x	x	x	x	x	x	x	x	x	x	x
1300	x	x	x	x	x	x	x	x	x	x	x	x	x
1400	x	x	x	x	x	x	x	x	x	x	x	x	x
1500	x	x	x	x	x	x	x	x	x	x	x	x	x

## Mīkstais savienojums



Izmērs AxB
300x150
400x200
500x250
500x300
600x300
600x350
700x400
800x500
1000x500

## Taisnstūra āra restes



Pieejamie izmēri atzīmēti tabulā ar x

H\B	100	150	200	300	400	500	600	700	800	900	1000	1100	1200
100	x	x	x	x	x	x	x	x	x	x	x	x	x
150	x	x	x	x	x	x	x	x	x	x	x	x	x
200	x	x	x	x	x	x	x	x	x	x	x	x	x
300	x	x	x	x	x	x	x	x	x	x	x	x	x
400	x	x	x	x	x	x	x	x	x	x	x	x	x
500	x	x	x	x	x	x	x	x	x	x	x	x	x
600	x	x	x	x	x	x	x	x	x	x	x	x	x
700	x	x	x	x	x	x	x	x	x	x	x	x	x
800	x	x	x	x	x	x	x	x	x	x	x	x	x
900	x	x	x	x	x	x	x	x	x	x	x	x	x
1000	x	x	x	x	x	x	x	x	x	x	x	x	x
1100	x	x	x	x	x	x	x	x	x	x	x	x	x
1200	x	x	x	x	x	x	x	x	x	x	x	x	x

